## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 7,134,726 B2

Page 1 of 3

APPLICATION NO.: 10/684933

**DATED** 

: November 14, 2006

INVENTOR(S)

: Juan Singla Casasayas

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the Title Page,

Item (75) should read as follows:

Item (75) Inventor: Juan Singla Casasayas, Martorelles

(ES)

On Sheet 4 of the drawings, Fig. 4 should be replaced with Fig. 4 as shown on attached


On Sheet 5 of the drawings, Fig. 5 should be replaced with Fig. 5 as shown on attached

Signed and Sealed this

Ninth Day of September, 2008

JON W. DUDAS Director of the United States Patent and Trademark Office U.S. Patent Nov. 14, 2006 Sheet 4 of 5

7,134,726 B2



**U.S. Patent** Nov. 14, 2006 Sheet 5 of 5

7,134,726 B2

